



Illinois Department of Transportation

Office of Finance & Administration / Bureau of Investigations & Compliance / Rm 323
2300 South Dirksen Parkway / Springfield, Illinois 62764

Non-Scheduled Inspection Report

N.I.R. # 96858SB

Owner/Operator	LINCOLNSHIRE - PRAIRIE VIEW SD 103			Date	5/17/2018
School District/Church Served	0			Phone	847-457-9317
Address	1370 RIVERWOODS RD			License Number	96858SB
City	LINCOLNSHIRE	County	LAKE	Unit Number	L1
Chassis Make	IC	Mileage-Actual	38,073	Inspector(s)	VI 88
Chassis Year	2016	Mileage-Due	47,313	Certificate of Safety	SHB50511442218
Contact Person	ANTHONY MENDOZA - DIR OF TRANS (A			Violation Decal #	0

Violations

	Defect #	Violations	Remarks
1	20	FRT RT CLEARANCE LIGHT OUT	0
2	0	0	0
3	0	0	0
4	0	0	0
5			
6			

No Visible Defects

Out-of-Service: Requires bus to be inspected at an Official Testing Station before being placed back in service. The owner/operator shall retain the original copy and return the second copy of this form to the Commercial Vehicle Safety Section after passing an inspection at an Official Testing Station.

New Certified Safety Sticker Applied by (Station Number and CST I.D Number Date

Three-Day Notice: Requires violation to be corrected within three working days if the non-scheduled inspection. Department Officers will return after the third day for a follow-up inspection and will complete this section. The owner/operator will retain the original copy, and the I.D.O.T. inspector will return the second copy to the Commercial Vehicle Safety Section.

Re-Inspection by I.D.O.T Due Inspector's Name/VI Number Mileage at the time of Inspection Date

Warning: Violations must be corrected within 30 days of the non-scheduled inspection. The owner shall complete this section, retain the original copy and return the second copy of this form to the Commercial Vehicle Safety Section after the repairs are completed.

Signature of Repairman

Authorized Official

Date

[Signature] / *MIDWEST TRANSIT KANKAKEE* 5-29-18

I acknowledge having received this report

Signature

Date



Illinois Department of Transportation

Office of Finance & Administration / Bureau of Investigations & Compliance / Rm 323
2300 South Dirksen Parkway / Springfield, Illinois 62764

Non-Scheduled Inspection Report

N.I.R. # 96853SB

Owner/Operator	LINCOLNSHIRE - PRAIRIE VIEW SD 103			Date	5/17/2018
School District/Church Served	0			Phone	847-457-9317
Address	1370 RIVERWOODS RD			License Number	96853SB
City	LINCOLNSHIRE	County	LAKE	Unit Number	L7
Chassis Make	IC	Mileage-Actual	37,318	Inspector(s)	VI 88
Chassis Year	2016	Mileage-Due	41,758	Certificate of Safety	SHB51208883118
Contact Person	ANTHONY MENDOZA - DIR OF TRANS (A			Violation Decal #	0

Violations

	Defect #	Violations	Remarks
1	8	AUX HTR EXHAUST PIPE BROKEN	REPLACE
2	0	0	0
3	0	0	0
4	0	0	0
5			
6		20	

No Visible Defects

Out-of-Service: Requires bus to be inspected at an Official Testing Station before being placed back in The C.S.T. shall complete this section and return the original and second copies to the bus owner/ operator. service. The owner/operator shall retain the original copy and return the second copy of this form to the Commercial Vehicle Safety Section after passing an inspection at an Official Testing Station.

New Certified Safety Sticker Applied by (Station Number and CST I.D Number Date

Three-Day Notice: Requires violation to be corrected within three working days if the non-scheduled inspection. Department Officers will return after the third day for a follow-up inspection and will complete this section. The owner/operator will retain the original copy, and the I.D.O.T. inspector will return the second copy to the Commercial Vehicle Safety Section.

Re-Inspection by I.D.O.T Due Inspector's Name/VI Number Mileage at the time of Inspection Date

Warning: Violations must be corrected within 30 days of the non-scheduled inspection. The owner shall complete this section, retain the original copy and return the second copy of this form to the Commercial Vehicle Safety Section after the repairs are completed.

Signature of Repairman Authorized Official Date

[Signature] *MIDWEST TRANSPORT KANKAKEE* *5-24-18*

I acknowledge having received this report

Signature

Date



Illinois Department of Transportation

Office of Finance & Administration / Bureau of Investigations & Compliance / Rm 323
2300 South Dirksen Parkway / Springfield, Illinois 62764

Non-Scheduled Inspection Report

N.I.R. # 96866SB

Owner/Operator	LINCOLNSHIRE - PRAIRIE VIEW SD 103		Date	5/17/2018	
School District/Church Served	0		Phone	847-457-9317	
Address	1370 RIVERWOODS RD		License Number	96866SB	
City	LINCOLNSHIRE	County	LAKE	Unit Number	L10
Chassis Make	IC	Mileage-Actual	32,038	Inspector(s)	VI 88
Chassis Year	2016	Mileage-Due	40,204	Certificate of Safety	SHB50209945818
Contact Person	ANTHONY MENDOZA - DIR OF TRANS (A		Violation Decal #	0	

Violations

Defect #	Violations	Remarks
1	30 FRT LOWER STOP ARM LEDS	0
2	0	0
3	0	0
4	0	0
5		
6		

No Visible Defects

Out-of-Service: Requires bus to be inspected at an Official Testing Station before being placed back in The C.S.T. shall complete this section and return the original and second copies to the bus owner/ operator. service. The owner/operator shall retain the original copy and return the second copy of this form to the Commercial Vehicle Safety Section after passing an inspection at an Official Testing Station.

New Certified Safety Sticker	Applied by (Station Number and CST I.D Number	Date
/	/	/

Three-Day Notice: Requires violation to be corrected within three working days if the non-scheduled inspection. Department Officers will return after the third day for a follow-up inspection and will complete this section. The owner/operator will retain the original copy, and the I.D.O.T. inspector will return the second copy to the Commercial Vehicle Safety Section.

Re-Inspection by I.D.O.T Due	Inspector's Name/VI Number	Mileage at the time of Inspection	Date
/	/	/	/

Warning: Violations must be corrected within 30 days of the non-scheduled inspection. The owner shall complete this section, retain the original copy and return the second copy of this form to the Commercial Vehicle Safety Section after the repairs are completed.

Signature of Repairman	Authorized Official	Date
<i>[Signature]</i>	MEDWEST TRANSIT KANKAKEE	5-24-18

I acknowledge having received this report

Signature	Date



Illinois Department of Transportation

Office of Finance & Administration / Bureau of Investigations & Compliance / Rm 323
2300 South Dirksen Parkway / Springfield, Illinois 62764

Non-Scheduled Inspection Report

N.I.R. # 96865SB

Owner/Operator	LINCOLNSHIRE - PRAIRIE VIEW SD 103			Date	5/17/2018
School District/Church Served	0			Phone	847-457-9317
Address	1370 RIVERWOODS RD			License Number	96865SB
City	LINCOLNSHIRE	County	LAKE	Unit Number	L11
Chassis Make	IC	Mileage-Actual	33,514	Inspector(s)	VI 88
Chassis Year	2016	Mileage-Due	41,397	Certificate of Safety	SHB50209944118
Contact Person	ANTHONY MENDOZA - DIR OF TRANS (A			Violation Decal #	0

Violations

	Defect #	Violations	Remarks
1	30	FRT LOWER LEDS OUT STOP ARM	0
2	41	SECURE BODY FLUID KIT	0
3	0	0	0
4	0	0	0
5			
6			

No Visible Defects

Out-of-Service: Requires bus to be inspected at an Official Testing Station before being placed back in service. The C.S.T. shall complete this section and return the original and second copies to the bus owner/ operator. The owner/operator shall retain the original copy and return the second copy of this form to the Commercial Vehicle Safety Section after passing an inspection at an Official Testing Station.

New Certified Safety Sticker _____ Applied by (Station Number and CST I.D Number _____ Date _____

Three-Day Notice: Requires violation to be corrected within three working days if the non-scheduled inspection. Department Officers will return after the third day for a follow-up inspection and will complete this section. The owner/operator will retain the original copy, and the I.D.O.T. inspector will return the second copy to the Commercial Vehicle Safety Section.

Re-Inspection by I.D.O.T Due _____ Inspector's Name/VI Number _____ Mileage at the time of Inspection _____ Date _____

Warning: Violations must be corrected within 30 days of the non-scheduled inspection. The owner shall complete this section, retain the original copy and return the second copy of this form to the Commercial Vehicle Safety Section after the repairs are completed.

Signature of Repairman _____ Authorized Official _____ Date _____

[Signature] / MIDWEST TRANSIT KANKAKEE / 6-6-18

I acknowledge having received this report _____

Signature

Date



Illinois Department of Transportation

Office of Finance & Administration / Bureau of Investigations & Compliance / Rm 323
2300 South Dirksen Parkway / Springfield, Illinois 62764

School Bus/CV Inspection Tally Sheet

Contractor, School District or Church		LINCOLNSHIRE - PRAIRIE VIEW SD 103			Date	May 17, 2018	
School District or Church Served		0			Phone	847-457-9317	
Address		1370 RIVERWOODS RD			Inspector(s)	VI 88	
City		LINCOLNSHIRE			Total Buses in Fleet	30	
County		LAKE			Contact	ANTHONY MENDOZA - DIR OF TRANS (AMENDOZA@D	
District Superintendent		SCOTT H WARREN			Superintendent E-Mail	SWARREN@D103.ORG	
					Total Buses Inspected	0	

License Number	Certificate of Safety	Unit Number	Chassis Make	Chassis Year	Body Make	Body Year	Actual Miles	Due Miles	N-O-T W-C	Defect Numbers	Violation	Violation Decal Number
968775B	5HB50209947418	L22	IC	2018	IC	2018	5,955	14,218	N	0 0		0
										0 0		
										0 0		
										0 0		
968795B	5HB50309955418	21	IC	2016	IC	2016	31,274	39,769	N	0 0		0
										0 0		
										0 0		
										0 0		
968805B	5HB50209949618	L20	IC	2016	IC	2016	35,477	42,529	N	0 0		0
										0 0		
										0 0		
										0 0		
968815B	5HB51108871318	L19	IC	2016	IC	2016	35,348	41,065	N	0 0		0
										0 0		
										0 0		
										0 0		
968825B	5HB50209929918	L18	IC	2016	IC	2016	29,523	38,023	N	0 0		0
										0 0		
										0 0		
										0 0		
968835B	5HB50209945018	L17	IC	2016	IC	2016	25,560	34,369	N	0 0		0
										0 0		
										0 0		
										0 0		
968845B	5HB51208875718	L15	IC	2016	IC	2016	27,901	35,381	N	0 0		0
										0 0		
										0 0		
										0 0		
968515B	5HB50209949118	L14	IC	2016	IC	2016	17,189	25,889	N	0 0		0
										0 0		
										0 0		
										0 0		
968515B	5HB50209949118	L14	IC	2016	IC	2016	28,958	37,501	N	0 0		0
										0 0		
										0 0		
										0 0		
968635B	5HB50208847318	L13	IC	2016	IC	2016	30,111	39,168	N	0 0		0
										0 0		
										0 0		
										0 0		
968645B	5HB50109933618	L12	IC	2016	IC	2016	30,652	38,777	N	0 0		0
										0 0		
										0 0		
										0 0		
968655B	5HB50209944118	L11	IC	2016	IC	2016	33,514	41,397	W	30 41	FRT LOWER LEDS OUT STOP ARM SECURE BODY FLUID KIT	0
										0 0		
										0 0		
										0 0		
968665B	5HB50209945818	L10	IC	2016	IC	2016	32,038	40,204	W	30	FRT LOWER STOP ARM LEDS	0
										0 0		
										0 0		
										0 0		
968585B	5HB50511442218	L1	IC	2016	IC	2016	38,073	47,313	W	20	FRT RT CLEARANCE LIGHT OUT	0
										0 0		
										0 0		
										0 0		
968685B	5HB50411480718	L29	IC	2016	IC	2016	30,354	39,682	N	0 0		0
										0 0		
										0 0		
										0 0		



Illinois Department of Transportation

Office of Finance & Administration / Bureau of Investigations & Compliance / Rm 323
2300 South Dirksen Parkway / Springfield, Illinois 62764

School Bus/CV Inspection Tally Sheet

Contractor, School District or Church		LINCOLNSHIRE - PRAIRIE VIEW SD 103				Date	May 17, 2018	
School District or Church Served		0				Phone	847-457-9317	
Address	1370 RIVERWOODS RD					Inspector(s)	VI 88	
City	LINCOLNSHIRE					Total Buses in Fleet	30	
County	LAKE	Contact	ANTHONY MENDOZA - DIR OF TRANS (AMENDOZA@D)				Total Buses Inspected	0
District Superintendent	SCOTT H WARREN			Superintendent E-Mail	SWARREN@D103.ORG			

License Number	Certificate of Safety	Unit Number	Chassis Make	Chassis Year	Body Make	Body Year	Actual Miles	Due Miles	N-O-T W-C	Defect Numbers	Violation	Violation Decal Number
96857SB	5HB50511485418	L3	IC	2016	IC	2016	29,978	39,749	N	0 0		0
										0 0		
										0 0		
96878SB	5HB50411480518	L28	IC	2016	IC	2016	23,122	32,666	N	0 0		0
										0 0		
										0 0		
96855SB	5HB51208877718	L5	IC	2016	IC	2016	35,242	41,406	N	0 0		0
										0 0		
										0 0		
96854SB	5HB51208887718	L6	IC	2016	IC	2016	23,266	31,347	C	20	FRT RT CLEARANCE ONLY 1 LED	0
										0 0		
										0 0		
96853SB	5HB51208883118	L7	IC	2016	IC	2016	37,318	41,758	W	8	AUX HTR EXHAUST PIPE BROKEN	0
										0 0		
										0 0		
96852SB	5HB50109332418	L8	IC	2016	IC	2016	25,178	32,878	N	0 0		0
										0 0		
										0 0		
96869SB	5HB51208887318	L9	IC	2016	IC	2016	30,234	37,794	N	0 0		0
										0 0		
										0 0		
96876SB	5HB50109918918	L23	IC	2018	IC	2018	9,504	14,722	N	0 0		0
										0 0		
										0 0		
0	0	0	0	0	0	0	-	-	0	0 0		0
										0 0		
										0 0		
0	0	0	0	0	0	0	-	-	0	0 0		0
										0 0		
										0 0		
0	0	0	0	0	0	0	-	-	0	0 0		0
										0 0		
										0 0		
0	0	0	0	0	0	0	-	-	0	0 0		0
										0 0		
										0 0		
0	0	0	0	0	0	0	-	-	0	0 0		0
										0 0		
										0 0		
0	0	0	0	0	0	0	-	-	0	0 0		0
										0 0		
										0 0		
0	0	0	0	0	0	0	-	-	0	0 0		0
										0 0		
										0 0		